Update V2.4 B4000+ Firmware

Introduction

This update addresses some minor sound bugs.
Please check our website from time to time, there you find
the most recent updates.

Keyclick

improved the keyclick effect:
- increased the maximum volume
- shorten the length of the click to make it more authentic

Percussion

When switched on, the percussion dominates the sound too
much. Therefore we set the minimum level much lower.

Chorus / Vibrato

When switched on, the percussion dominates the sound too
much. Therefore we set the minimum level much lower.

Illegal CC commands

Some unassigned MIDI-CC caused the B4000+ to stop
working. This bug is fixed now.

FERROFISH
advanced audio applications